Reg. No. :						
KEG NO .						
110g. 110						
0		1	1		1	

(b) Resistance of armature circuit

(d) All of the above

Question Paper Code: 43302

B.E. / B.Tech. DEGREE EXAMINATION, DEC 2020

Third Semester

Electrical and Electronics Engineering

	14UEE302 - DC MACH	INES AND TRANSFORMERS						
	(Regu	llation 2014)						
D	Ouration: One hour	Maximum: 30 Marks						
	PART A -	$(6 \times 1 = 6 \text{ Marks})$						
	(Answer any six o	f the following questions)						
1.	The principle of dynamically induced e	ne principle of dynamically induced emf is utilised in						
	(a)) Choke	(b) Transformer						
	(c) Generator	(d) Thermocouple						
2.	Hysteresis loss can be minimised by selecting a magnetic material having							
	(a) large B/H loop area	(b) High resistivity						
	(c) High retentivity	(d) Low hysteresis coefficient						
3.	Which generator has poorest voltage regulation?							
	(a) Series	(b) Shunt						
	(c) Long shunt compound	(d) Short shunt compound						
4.	Interpole winding is connected in							
	(a) Series with armature	(b) Series with main poles						
	(c) Parallel with armature	(d) Parallel with main poles						

5. The speed of the dc motor can be controlled by varying

(a) Its flux per pole

(c) Applied voltage

6.	The direction of rotation of conductors of a	DC motor can be determined by							
	(a) Ampere law	(b) Fleming's left hand rule							
	(c) Fleming's right hand rule	(d) Lenz's law							
	If a transformer primary is energised put voltage will be	from a square wave voltage sour	rce, its						
	(a) Square wave	(b) Sine wave							
	(c) Pulse wave	(d) Triangular wave							
8.	Transformer action requires a								
	(a) Constant magnetic flux	(b) Increasing magnetic flux							
	(c) Alternating magnetic flux	(d) Alternating electric flux							
9.	One of the main advantages of Swinburne's	test is that it							
	(a) its applicable for shunt motors	(b) needs one running cost							
	(c) its very economical and convenient	(d) ignore any charge in iron	n loss						
10.	The main purpose of performing open-circu	it test on a transformer is measure its							
	(a) cu loss	(b) core loss							
	(c) total loss	(d) insulation resistance							
	PART – B (3 x 8	8= 24 Marks)							
	(Answer any three of the	e following questions)							
11.	. Derive an expression for mechanical force developed by magnetic field.								
12.	2. Explain with a neat sketch, the construction of a dc machine.								
13.	Sketch and explain the speed-current, sp	peed-torque and torque-current							
	characteristics of a shunt motor, serie								
14.	4. Draw the no-load phasor diagram of a transformer and explain.								
15.	Explain any two methods of testing of DC machines. (8)								