Reg. No. :					
1106.1					

Question Paper Code: 47403

B.E. / B.Tech. DEGREE EXAMINATION, MAY 2022

Seventh Semester

Electronics and Communication Engineering

14UEC703 - MICROWAVE ENGINEERING

(Regulation 2014)

Duration: Three hours Maximum: 100 Marks

Answer ALL Questions

PART A -
$$(10 \times 1 = 10 \text{ Marks})$$

- 1. To couple two waveguides a choke flange may be used
 - (a) As it is simpler than any other method of joining
 - (b) To help the alignment of the waveguides
 - (c) To compensate for discontinuities at the joint
 - (d) T increase the bandwidth of the system
- 2. The waveguide tuning component, which is not easily adjustable is,
 - (a) Screw (b) Iris (c) Stub
- (d) Plunger
- 3. TRAPATT diode is preferred over IMPATT diode because of
 - (a) High η

- (b) Less sensitivity to harmonics
- (c) Lower noise
- (d) Ability to operate at higher frequencies
- Two entities that are combined to form a Magic Tee are 4.
 - (a) One H and one E plane tee
- (b) One Hand two E plane tees
- (c) Two Hand two plane tees
- (d) Two H and one E plane tee
- The efficiency (η) of the klystron can be calculated as 5.
 - (a) $\eta = P_{ac} + P_{dc}$ (b) $\eta = P_{ac} + P_{dc}$ (c) $\eta = P_{ac} P_{dc}$ (d) $\eta = P_{ac} / P_{dc}$

(c) Coaxial magnetron (d) Travelling wave magnetron 7. The fabrication of microstrip line is done by (a) Photo etching (b) Printed circuit technique (c) Oxidation (d) Cladding 8. Processing in MMICs is done by (a) Ion implantation (b) Net list generation (c) Floor planning (d) None of the above 9. A loss less line of characteristics impedance Z ₀ is terminated in pure reactance of –jZ ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2245°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S ₁₁ = 0.2∠ 90° S ₂₂ = 0.2 ∠90° S ₁₂ = 0.5 ∠90° S ₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	6.	The microwave (a) Reflex	-	ses an axial magnetic field (b) CFA	and radial electric field is			
7. The fabrication of microstrip line is done by (a) Photo etching (b) Printed circuit technique (c) Oxidation (d) Cladding 8. Processing in MMICs is done by (a) Ion implantation (b) Net list generation (c) Floor planning (d) None of the above 9. A loss less line of characteristics impedance Z ₀ is terminated in pure reactance of –jZ ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2245°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S ₁₁ = 0.22 90° S ₂₂ = 0.2 290° S ₁₂ = 0.5 20° S ₂₁ = 0.5 20° (i) Determine whether the network is lossy or not. (iii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)		` '	•	` '	ave magnetron			
(c) Oxidation (d) Cladding 8. Processing in MMICs is done by (a) Ion implantation (b) Net list generation (c) Floor planning (d) None of the above 9. A loss less line of characteristics impedance Z ₀ is terminated in pure reactance of –jZ ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2∠45°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S ₁₁ = 0.2∠90° S ₂₂ = 0.2 ∠90° S ₁₂ = 0.5 ∠90° S ₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	7.	` '	•	` ′	.,			
 8. Processing in MMICs is done by (a) Ion implantation (b) Net list generation (c) Floor planning (d) None of the above 9. A loss less line of characteristics impedance Z₀ is terminated in pure reactance of -jZ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2∠45°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network. (16) 		` ´	<u> </u>	, í	t technique			
(a) Ion implantation (b) Net list generation (c) Floor planning (d) None of the above 9. A loss less line of characteristics impedance Z₀ is terminated in pure reactance of -jZ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2∠45°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠90° S₂₂ = 0.2∠90° S₁₂ = 0.5∠90° S₂₁ = 0.5∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)		(c) Oxidation	on	(d) Cladding				
(c) Floor planning (d) None of the above 9. A loss less line of characteristics impedance Z₀ is terminated in pure reactance of −jZ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2∠45°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠ 90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	8.	Processing in M	MICs is done by					
 9. A loss less line of characteristics impedance Z₀ is terminated in pure reactance of -jZ₀ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is 0.2∠45°.The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠ 90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) 		` ´						
reactance of $-jZ_0$ value.VSWR is (a) 10 (b) 2 (c) Infinity (d) 1 10. The reflection coefficient on a line is $0.2 \angle 45^0$. The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by $S_{11} = 0.2 \angle 90^\circ S_{22} = 0.2 \angle 90^\circ S_{12} = 0.5 \angle 90^\circ S_{12} = 0.5 \angle 90^\circ S_{11} = 0.5 \angle 90^\circ S_{11} = 0.5 \angle 90^\circ S_{11} = 0.5 \angle 90^\circ S_{12} = 0.5 \angle 90^\circ $		(c) Floor planning		(d) None of the above				
10. The reflection coefficient on a line is 0.2∠45°. The SWR is (a) 0.8 (b) 1.1 (c) 1.2 PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠90° S₂₂ = 0.2∠90° S₁₂ = 0.5∠90° S₂₁ = 0.5∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	9.			spedance Z_0 is terminated i	n pure			
PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by $S_{11} = 0.2 \angle 90^{\circ} S_{22} = 0.2 \angle 90^{\circ} S_{12} = 0.5 \angle 0^{\circ}$ (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)		(a) 10	(b) 2	(c) Infinity	(d) 1			
PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S ₁₁ = 0.2∠ 90° S ₂₂ = 0.2 ∠90° S ₁₂ = 0.5 ∠90° S ₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	10.	The reflection	coefficient on a line i	is $0.2 \angle 45^0$. The SWR is				
PART - B (5 x 2 = 10 Marks) 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠ 90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)					(d) 1.5			
 11. What are hybrid couplers? 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁1 = 0.2∠ 90° S₂2 = 0.2 ∠90° S₁2 = 0.5 ∠90° S₂1 = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or		(a) 0.8	(b) 1.1	(c) 1.2				
 12. List the applications of Gunn diode. 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠ 90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or			PART - I	B $(5 \times 2 = 10 \text{ Marks})$				
 13. Compare O-type tube and M-type tube 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠ 90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or	11.	What are hybrid	d couplers?					
 14. What is double stub matching? 15. What are the errors in impedance measurement? PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by S₁₁ = 0.2∠ 90° S₂₂ = 0.2 ∠90° S₁₂ = 0.5 ∠90° S₂₁ = 0.5 ∠0° (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or	12.	List the applica	tions of Gunn diode.					
PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by $S_{11} = 0.2 \angle 90^{\circ} S_{22} = 0.2 \angle 90^{\circ}$ $S_{12} = 0.5 \angle 90^{\circ} S_{21} = 0.5 \angle 0^{\circ}$ (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	13.	Compare O-typ	e tube and M-type tul	be				
PART - C (5 x 16 = 80 Marks) 16. (a) The S-parameters of a two-port network are given by $S_{11} = 0.2 \angle 90^{\circ} S_{22} = 0.2 \angle 90^{\circ}$ $S_{12} = 0.5 \angle 90^{\circ} S_{21} = 0.5 \angle 0^{\circ}$ (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)	14.	What is double	stub matching?					
16. (a) The S-parameters of a two-port network are given by $S_{11} = 0.2 \angle 90^{\circ} \ S_{22} = 0.2 \ \angle 90^{\circ} \ S_{12} = 0.5 \ \angle 90^{\circ} \ S_{21} = 0.5 \ \angle 0^{\circ}$ (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or	15.	What are the er	rors in impedance me	easurement?				
$S_{11} = 0.2 \angle 90^{\circ} S_{22} = 0.2 \angle 90^{\circ}$ $S_{12} = 0.5 \angle 90^{\circ} S_{21} = 0.5 \angle 0^{\circ}$ (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16)			PART - C	$C(5 \times 16 = 80 \text{ Marks})$				
$S_{12} = 0.5 \angle 90^{\circ} S_{21} = 0.5 \angle 0^{\circ}$ (i) Determine whether the network is lossy or not. (ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or	16.	(a) The S-parar	neters of a two-port n	etwork are given by				
(i) Determine whether the network is lossy or not.(ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or		$S_{11} = 0.2 \angle$	$90^{\circ} \text{ S}_{22} = 0.2 \angle 90^{\circ}$					
(ii) Is the network symmetrical and reciprocal? Find the insertion loss of network.(16) Or			=-					
Or		(i) Determin	ne whether the networ	k is lossy or not.				
		(ii) Is the net	twork symmetrical an	d reciprocal? Find the inse	ertion loss of network.(16)			
(b) Draw a diagram and explain in detail about four port circulator (16)				Or				
(10)		(b) Draw a dia	gram and explain in d	etail about four port circul	ator (16)			

17. (a)) Explain the operating principle of a Gunn diode. Describe its domain	
	formation and various modes of operations.	(16)
	Or	
(b	(i) Draw the construction and explain the working of IMPATT diode.	(8)
	(ii) Explain the working of TRAPATT Diode.	(8)
18. (a) Explain the π mode of Oscillations in a Magnetron and derive the Hull cut-or	ff
	equations of a Magnetron.	(16)
	Or	
(b)	Explain the concept and derive the expression for Bunching process.	(16)
19. ((a) Explain the various stages involved in Monolithic Microwave Integrated C technology.	Circuits (16)
	Or Or	(10)
(b) Draw a flow chart for MMIC fabrication process and discuss in detail.	(16)
20. (a) (i) Explain the impedance measurement technique using slotted line and reflectometer.	(8)
	(ii) Explain the measurement of high VSWR with the help of block diagram.	(8)
	Or	
(b)) Describe the measurement of power at microwave frequencies.	(16)